

## **NONCOMPLIANCE REPORT**

Attachment to Atlanta Gold Corporation's Discharge Monitoring Reports

**February 2020** – The first week's effluent arsenic sample was in compliance and then there was a slight bump to 13 ug/L but the last week's sample went down to 11 ug/L.

**March 2020** – Although the five weeks of effluent samples were slightly over 10 ug/L, ranging from 11 ug/L to 14 ug/L, they were still less than the baseline sample of 28 ug/L.

**April 2020** – The effluent arsenic sample for the first week was 16 ug/L. However, the following weeks, it decreased slightly so that by the end of the month it was down to 14 ug/L. The samples for the week of April 20<sup>th</sup> were not submitted to the lab due to a miscommunication with the delivery person and not being able to submit the samples within the appropriate time period. This miscommunication has been resolved and should not happen in the future.